




# Gallery & Exhibit Wall

1. Open front legs and slide carriage bolt into main support channel by rotating crossbar upwards (fig. A).
2. Secure second leg by sliding carriage bolt into crossbar notch (fig. B).
3. Extend back leg support and secure with wingnut (fig. C).
4. Slide supports down main channel with ridges facing upwards (fig. D).



## Applicable Products:

GE-1

